

100029256 REVISIONS 2 CTION S 03 SURVE 2 6 0 A 2 6 0 A 2 6 0 A 1. THIS IS NOT A BOUNDARY SURVEY AND SHOULD NOT BE USED AS SUCH. ЮF 2. SURVEY COORDINATE IS RELATIVE AND MAY HAVE TO BE MOVED AND ROTATED TO MATCH STATE PLANE AZ CENTRAL ZONE NAD 1983 DATUM. EXHIBI' ALL MONUMENTATION SHOWN HEREON WAS ACCEPTED UNLESS OTHERWISE NOTED 68 RTION ΖЩ 1 NORTH 1/4 CORNER OF SECTION 23 FOUND GLO. o 13 BASI 3 FOUND REBAR 0.29' EAST OF THE MONUMENT LINE. 4 FOUND PVC PIPE 0.79' SOUTH OF THE NORTH BOUNDARY CORNER. Mapping FOUND REBAR WITH NO CAP 0.96' EAST OF 6 FOUND REBAR WITH CAP MARKED 27738. Since 1988 SUITE 4 FOUND REBAR 0.76' NORTH OF THE TIE LINE. FOUND T POST 0.71' NORTH AND 0.92' EAST OF THE SOUTHWEST BOUNDARY CORNER. and FOUND T POST 0.21' NORTH OF THE SOUTHEAST BOUNDARY CORNER. ßu zona Surveyi Confid **Absolute** 2440 Ari SURVEYOR'S STATEMENT: I, LANCE C. DICKSON, BEING A LICENSED LAND SURVEYOR IN THE STATE OF FIELDWORK BY : LCD ARIZONA HEREBY STATE THAT THIS MAP OR PLAT AND THE SURVEY ON WHICH IT WAS BASED WAS MADE UNDER MY SUPERVISION AND IT IS CORRECT TO DRAWN BY : LCD THE BEST OF MY KNOWLEDGE AND THAT THE MONUMENTS SHOWN HEREON DO

> 46643 LANCE C. DICKSON DATE

DATE : 04/11/22 SHEET NO. OF

LCD

P22-126

CHECKED BY :

JOB #

SEMS-RM DOCID #